

## PERFORMANCE COMPARISON PORCELAIN PAVERS VS. COMPETITOR OUTDOOR PAVING MATERIALS

FEATURES	FRONTIER20 PORCELAIN PAVERS	WOOD PAVERS	CLAY BRICK	CIP (CAST IN PLACE) CONCRETE	CONCRETE PAVERS	NATURAL STONE
Stainable	No	Yes	Yes (Highly)	Yes	Yes	Yes (Highly)
Freeze Thaw Proof	Yes	No	No	No	No	No
Salt Resistant	Yes	No	Salt Will Degrade	No	No	No
Acid Resistant	Yes	No	Acid Will Burn	No	No	No
Scratch Resistant	Highly	No	Somewhat	No	No	No
Moisture Absorption	< 0,5%	Highly Varried	5%	5%	5-10%	≥ 5%
Easy To Repair	Yes	Yes	No	Can Not	No	No
Uv Resistant	Unaffected	No	Yes	If Sealed	Yes/No	Unaffected
Needs Sealed	Never	Yes	Recommended	Recommended	Recommended	Recommended
Pressure Washer Safe	> 1500 PSI	No	Not Recommended	> 1500 PSI	No	No
Environmentally Friendly	Facility 98% Green	Many Exotic Rainforest Species	No	Large Carbon Foot Print	Possible Fly Ash Content	Mined Or Imported
Recycled Content	5% In Each Paver	No	Not Possible	Not Possible	If Possible Less Than 5%	Not Possible
TORONTO 115 Carnarv Toronto, ON T 416 413 9	M6M 3C9 Trov	tutz Drive, Ste MI 48084	Plea	ase note, all spe by the manufactu		

Email: mail@cercantile.com Website: www.cercantile.com

PHYSICAL PROPERTIES	TEST ASTM	NORTH AMERICAN STANDARD A137.3*	RESULTS	
Water absorption *	C373	≤ 0.5%	COMPLY WITH ANSI A137.3	
DCOF Average dynamic coefficient of friction **	ANSI A.326.3	As reported	EW - Exterior, Wet	
	EN 16165 (EX DIN 51097)		A+B+C	
Skid Resistance	EN 16165 (EX DIN 51130)	-	R11	
Resistance to freeze/thaw cycling *	C1026	As reported	RESISTANT	
Resistance to thermal shock	C484	As reported	RESISTANT	
Warpage (edge)	C485	Warpage $\pm$ 0.4% or $\pm$ 0.05 in	COMPLY WITH ANSI A137	
Warpage (diagonal)	C485	Warpage $\pm$ 0.4% or $\pm$ 0.07 in	COMPLY WITH ANSI A137	
Wedging	C502	± 0.25% or ± 0.03 in	COMPLY WITH ANSI A137	
Chemical resistance	C650	As reported	UNAFFECTED	
* Resistance to stain	C1378	As reported	UNAFFECTED	
Thickness	C499	Range: 0.04 in	COMPLY WITH ANSI A137	
Breaking strength	C1050	2000 lbf	COMPLY WITH ANSI A137	
Module of Ropture	C1050	5000 psi	COMPLY WITH ANSI A137	

\* Average values referred to our production and related to the matt finish of the product.

to check the lot you are interested in purchasing.

- Be sure to use pavers belonging to the same caliber.

- Test results are available on request.

## WARNINGS.

- Failure to adhere to the manufacturer's instructions for installation of slabs on raised pedestal systems may result in serious injury.

\*\*

USGBC

MEMBER







210

F 416 413 9652

T 248 643 6520

F 248 643 6523

## **PORCELAIN PAVER PERFORMANCE** DATA (20 mm)

\*\* As far as values relating to the matt finish of the product and to tests carried out by certified external laboratories whose results are available upon request at Headoffice, we are willing

Outdoor pavings installed unglued above the ground level are subject to the action of the wind, with the risk, in some cases, of becoming airborne. The manufacturer recommends to require the assistance of a qualified professional in order to check the suitability of the installation system above the ground adopted, in accordance with the local laws and regulations and the conditions of use. Failure to do so could result in serious injury or property damage.
If the application of the 20 mm slabs requires the ceramic product used in structural installations, the project engineer and/or customer must carefully assess the project requirements with regard to the technical specifications of the slabs. to prevent the risk of damage or injury, the manufacturer recommends: with regard to a raised floor installation and to follow table for raised installation provided below. in certain conditions, reinforcing must be applied on the back of the slabs (double fiberglass mesh) supplied and applied by the manufacturer; with reference to any dry installation system of flooring above the ground level, the manufacturer recommends to comply with local regulations and conditions of use with regard to comply with these recommendations may lead to improper use of the product and could cause serious damage or injury. Failure to adhere to the manufacturer's instructions for installation of slabs on raised needed to ever the rearror used manufacturer.









